

Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program Sanitary Sewer Overflow (SSO)/Bypass Notification Form

Comments

FOR DEP USE ONLY

Tax Identification Number

Facility Information III, MA WPCF			MA01012	31		
eporting Sewer Authority			Permit #			
Authorized Representative	Transmitting For	m:				
		Varjabedian			781-925-0906	
am rst Name	•	Last Name		-	Telephone No.	
			a. aniaha	dian Ourondardaurra	on com	
ant Manager tle			E-mail A	dian@woodardcurra ddress	in.com	
ue			2=.101802.00			
. Phone Notifications:						
MassDEP staff contacted:		David		Burns		53
Contacted By	Email	First Name		Last Name		
Date/Time contacted:		05/27/2018 11:23 AM				
Contacted by:				Turin		
EPA staff contacted: Contacted by:	Email	David First Name		Turin Last Name		-
Contacted by.	Cilidii	Filst Name		2001/10/110		
Date/Time EPA contacte	d:	05/26/2018 11:23 AM				
. Board of Health contacted		Joyce		Sullivan Last Name		-
Contacted by:		First Name		Last Name		
Date/Time contacted:		05/27/2018 11:23 AM				
. Dir. Of Wastewater Oper.	Hull Sewer Dept.	John		Struzziery		_
Contacted by:		First Name		Last Name		
Date/Time contacted:		05/26/2018 15:10 PM				
- 300 11110 751110					C Th. MART MAY MANAGE	
Others notified:	Harborma	ster / Shelfish Warden - Kur tion Agent - Chris Krahforst,	t Bornheim, Di	vision of Marine Fish	neries - Ryan Joyce,Hull	
. Outcio nounca.	Conserva	tion Agent - Chris Krantorst,	DPW Director	- Jilli Dow, Town IVI	allager - Frillip Lerrinos	



Massachusetts Department of Environmental Protection Bureau of Resource Protection – Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass Notification Form

C	SSO Information				
1.	SSO Discovered: By: Joe Basler		Date and Time	5/26/2018 12:30	
2.	SSO Stopped Date and Tin	ne05/26/20	18 07:45 PM		
3.	SSO Discharge from:	Other Sanitary Manhole, Pump Station, Backup into proper Back up from gravity sewer line up to	T	Newton St. Sewer line runs along side of road in this	area
4.	Specify: SSO Discharge to:	Ground Surface Ground Surface, Direct to Receiving Water, Catch Ba			aica.
	Specify:			a constraint discount of the stands.	
Lo	Approx lo	cation is 13 Newton Street, which is t	the rear of property of 57	Main St.	
	X,Y Coordinates 42303358	, -70.910825	(Description of discharg	e site or closest address)	
5.	Estimated SSO Volume at t	ime of this Report:	< 75 gallons		
	Method of Estimating Volun	ne:	Visual; most contained ground surface.	to with-in the excavated trench area. Difficult to estim	ate & small amoun
		Other Method:			
6.	Cause of SSO Event:	Sewer System Blockage,Pipe Collap	pse,Root Intrusion	M	
F	Rain Event, PS Failure	e, Insufficient Capacity in S	ystem, Treatment I	Jnit failure , Sewer System Blockage, Pip	e Collapse,
	Specify:				
7.	Corrective Actions :		ine was dye tested and s	pipe breaks, and roots caused backup. Approximate ome flow was getting by at Main Street. Jetted approxugh the repaired section.	
	Impact Area cleaned and/o	or disinfected: Yes		Corrective Actions Completed: Yes	
	Details:	Affected area, soil was excavated a	nd liquid stayed within tre	nch. Lime applied to all surface areas, upon completion	on.

to.



Massachusetts Department of Environmental Protection

Bureau of Resource Protection - Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass Notification Form


D. Comments/Attachments/Follow-up

Additional comments and planned actions:

Camera inspection to be made of this line. If any other defects found, corrective plan to repair will be made.

I wish to provide the following:


Attachement



GIS Map



trench bed prep, before new section installed



Excavated trench and dyed water



repaired section with cleanout



Massachusetts Department of Environmental Protection

Bureau of Resource Protection - Watershed Permitting Program

Sanitary Sewer Overflow (SSO)/Bypass

Notification Form

E. Certification Statement

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

ann Vaijhedin	5/31/2018	
Signature of Authorized Representative	Date Signed	

Please keep a copy of this report for your records. When submitting additional information, include the MassDEP Incident Number from this report.

MassDEP Regional Office and EPA Telephone and Fax Numbers:

Northeast Phone: 978-694-3215 Fax: 978-694-3499 Southeast Phone: 508-946-2750 508-947-6557 Fax: Central Rt Phone: 508-792-7650 Fax: 508-792-7621 Western F Phone: 413-784-1100 413-784-1149 Fax: EPA Cont Phone: 617-918-1870 617-918-0870 Fax: DEP 24-h Phone: 888-304-1133

Town of Hull Wastewater Treatment Plant

1111 Nantasket Avenue Hull, MA 02045 (781) 925-1207




NPDES Permit # MA0101231

Unauthorized Discharge Summary to Surface Waters Newton Street [5-26-18]

Location (address or latitude and longitude);	On SSO form
Date and Time unauthorized discharge began;	On SSO form
Date and Time unauthorized discharge stopped;	On SSO form
Source of the notification (e.g., property owner, field crew, police);	Odor complaint call into to Sewer Department On- call pager. Staff responded to Newton Street where leak to ground surface appeared to be sewage.
Type of asset from which the unauthorized discharge occurred (e.g., station, manhole, main);	6-inch VC pipe blockage at Main & Newton as well as blockages in line up towards the leak location. At leak location VC pipe condition was poor and had holes in pipe.
Estimated gallons released;	Difficult to estimate < 75 gallons, much of volume contained within trench, and lower amount to ground surface.
Method used to estimate volume;	Best estimate based upon visual.
Cause of the unauthorized discharge, (blockage or break; mechanical, electrical, or structural failures);	Blockage in sewer line at MH 20045 [Main/Newton] and in between this manhole and MH 20036 on Newton Street. Root intrusion and pipe breaks in VC pipe segments at leak location.
If caused by a blockage, identify the type of blockage (e.g., grease, rags, debris);	Silt & debris
If caused by a mechanical, electrical, or structural failure, the date of the last inspection, maintenance, or repair of the failed asset;	NA
Did the release reach any portion of the Town's Municipal Separate Storm Sewer System ("MS4").	No release to MS4; no storm drains in this area.


If the release occurred to the ground, provide the location of the nearest down-gradient catch basin and the name of the receiving water to which the catch basin discharges;	No near-by down-gradient catch basins. Leak was off the side of the street surface and very localized.
Did the release reach a wetland or surface water? If so, include the name and exact location where?	No
Measures taken to minimize the volume and duration of the unauthorized discharge;	See corrective action on SSO form
Measures taken to clean the area where the unauthorized discharge occurred;	Excavation area kept to a minimum and followed with clean up & lime applied.
Corrective actions taken to prevent reoccurrence of unauthorized discharges at the same location;	Sewer line jetted to remove debris from line, and additional camera inspection scheduled & performed on 5/31/18.
Date of the last unauthorized discharge in the same general location;	Unknown

Newton St.



SSO - LEAN caused by downstream
blockage + broken pipe SEGMENTS
AT leak location






CLEANOUT LOCATION

Looking down Newton St. toward MAIN ST.



6" sewer line that had break + leak LOCATION





MH20045 - JETTING UP NEWTON ST. MAIN ST/NEWTON ST.

CAMERA SHOWING BLOCKAGE AT MH 20045

Aram Varjabedian

From:

Aram Varjabedian

Sent:

Sunday, May 27, 2018 12:23 PM

To:

Aram Varjabedian; Berardinelli, Terri; Bill Boornazian; david.burns

(david.burns@state.ma.us); Dow, James (jdow@town.hull.ma.us); Frank Cavaleri; jstruzziery (jstruzziery@town.hull.ma.us); jsullivan (jsullivan@town.hull.ma.us);

kbornheim (kbornheim@town.hull.ma.us); Krahforst, Chris (ckrahforst@town.hull.ma.us);

Lemnios, Philip (plemnios@town.hull.ma.us); O'Connor, Carol; Robert Scott

(rscott@woodardcurran.com); Turin, David (Turin.David@epa.gov); Joyce, Ryan (FWE)

(ryan.joyce@state.ma.us)

Robert Scott

Joyce, Ryan (FWE) (ryan.joyce@state.ma.us)

(rscott@woodardcurran.com)

Turin, David (Turin.David@epa.gov)

Subject:

Preliminary SSO Reprt notification - Hull, MA - MA0101231

Attachments:

map_052618_Newton_St.pdf

Tracking:

Recipient	Delivery	Read
Aram Varjabedian	Delivered: 5/27/2018 12:23 PM	Read: 5/27/2018 12:46 PM
Berardinelli, Terri		
Bill Boornazian	Delivered: 5/27/2018 12:23 PM	
david.burns (david.burns@state.ma.us)		
Dow, James (jdow@town.hull.ma.us)		
Frank Cavaleri	Delivered: 5/27/2018 12:23 PM	Read: 5/27/2018 12:45 PM
jstruzziery (jstruzziery@town.hull.ma.us)		
jsullivan (jsullivan@town.hull.ma.us)		
kbornheim (kbornheim@town.hull.ma.us)		
Krahforst, Chris		
(ckrahforst@town.hull.ma.us)		
Lemnios, Philip		
(plemnios@town.hull.ma.us)		
O'Connor, Carol		

Delivered: 5/27/2018 12:23 PM

Read: 5/27/2018 2:07 PM

Good morning:

This email is to notify you that there was a sewer blockage on Newton Street in Hull on Saturday 5/26, that resulted in a small release to the ground surface on the side of the road on Newton St. The release, limited to the ground surface on side of the road, did not reach any down gradient storm drains. The Newton Street area is bordered by #57 and #69 Main Street.

As a result of the department's investigation, a sub-contractor was called in, as well as a vactor/jetter truck. The area where the leak was occurring was small and intermittent and the notification had come in initially as an odor complaint. The affected area was

excavated and defects in the 6-inch vitrified clay pipe were found and root intrusion into the pipe also existed. These issues were corrected. The downstream blockage where Newton St. meets Main Street [MH 20045] was cleared, with approximately 200 feet of sewer line jetted upstream on Newton St. from the Main Street manhole.

A full SSO Notification Report Form will be completed and submitted.

Sincerely,

Aram
Aram Varjabedian
Plant Manager
Hull Wastewater Treatment Facility
1111 Nantasket Avenue |Hull, MA 02045
Phone 781.925.0906 | Fax 781.925.3056 | Cell 339.214.8334
www.woodardcurran.com

